

## Product Recall

### Wk 12 3 0371/08 Motor vehicles 4-wheeled motorised ATV quad bike

**NO PICTURE AVAILABLE**

Brand: POLARIS

Type/number of model:

- Sportsman 500s. Model year 2005
- Scrambler ATVs. Model Year 2005
- Sportsman 400s. Model Year 2005 and 2006
- Scrambler 500 4x4s. Model Year 2006
- Sportsman 450s. Model Year 2005
- Sportsman 600s. Model Year 2005 and 2006
- Sportsman 6x6s. Model Year 2005 and 2006
- Carbureted. Model Year 2005
- Sportsman 700s. Model Year 2005
- Carbureted 2005. Model Year 2005 - Sportsman MV7.

Description: The recall concerns 2004, 2005 and 2006 model year vehicles.

#### **Fire**

The product poses a risk of fire because certain vehicles were assembled with Electronic Control Modules (ECMs) that may contain a defective fan Field Effect Transistor (FET). The fan FET is an electrical component involved with the ATV's cooling fan function. In most instances when the fan FET fails, the vehicle battery will drain and the vehicle will not start. In some instances, the defective fan FET can cause the ECM to fail and then overheat. If this were to occur, excessive heat could occur inside the ECM which could, in infrequent circumstances, progress to fire.

Country of origin: United States