

Environmental Statement
Volume 2: Figures

**Land to the North of the
Railway Line, Rhoose,
Vale of Glamorgan**

**The National Assembly for Wales
Bellway plc
Persimmon Homes (Wales) Ltd**

2008

Study team
White Young Green
Capita Symonds
Kernon Countryside Consultants
Cotswold Archaeology

LIST OF FIGURES (PROVIDED IN VOLUME 2)

Figure 1.1	Location plan
Figure 1.2	Site location
Figure 2.1	Urban context
Figure 3.1	Development framework
Figure 4.1	Agricultural Land Classification
Figure 6.1	Site location
Figure 6.2	Recorded archaeological sites within and around the site
Figure 6.3	The historic landscape
Figure 6.4	Photographs 6.1 and 6.2
Figure 6.5	Photograph 6.3
Figure 8.1	Ecological survey
Figure 8.1A	Additional ecological survey
Figure 8.2	Breeding bird survey: April and July 2005
Figure 8.3	Breeding bird dawn survey: May 2007
Figure 8.4	Breeding bird dawn and dusk survey: June 2007
Figure 8.5	Breeding bird dawn survey: July 2007
Figure 9.1	Landscape context
Figure 9.2	Site survey
Figure 9.3	Photographs 1
Figure 9.4	Photographs 2
Figure 9.5	Photographs 3
Figure 9.6	Visual context
Figure 9.7	Appraisal photographs
Figure 9.8	Photographs 4
Figure 9.9	Photographs 5
Figure 9.10	Landscape character
Figure 9.11	Existing vegetation
Figure 10.1	Noise survey locations