

TAG Journey Quality Impacts Worksheet

Factor	Sub-factor	Better	Neutral	Worse
Traveller Care	Cleanliness			
	Facilities			
	Information			
	Environment			
Travellers' Views	-			
Traveller Stress	Frustration			
	Fear of potential accidents			
	Route uncertainty			

Reference Source

10013270-ARC-XX-XX-DR-HE-0001 - East Alignment
 10013270-ARC-XX-XX-DR-HE-0002 - East Alignment with Env Cons
 10013270-ARC-XX-XX-DR-HE-0003 - East Alignment with Flood Zones
 10013270-ARC-XX-XX-DR-HE-0004 - East Alignment Longsection
 20180223_DemFlowDiff_ACVvsACU_2036
 DMRB 11.3.9.2 (travellers' views) and 11.3.9.3 (traveller stress)

Summary Assessment Score

High (more than 10,000 users per day affected).

Qualitative Comments

See the Stage Two Outline Business Case report.

TAG Security Impacts Worksheet

Security Indicator	Relative importance	Without scheme	With scheme
	(High/Medium/Low)	(Poor/Moderate/High)	(Poor/Moderate/High)
Site perimeters	Low	Poor	Moderate
Entrances and exits	n/a	n/a	n/a
Formal surveillance	Low	Poor	Poor
Informal surveillance	High	Poor	Moderate
Landscaping	Medium	Poor	Moderate
Lighting and visibility	Medium	Poor	Moderate
			(High for cyclists/ pedestrians)
Emergency call	Medium	Poor	Poor

Approximate Number of Users Affected

More than 10,000.

Reference Source

10013270-ARC-XX-XX-RP-HE-0001 - M4 J34 - A48 WeITAG Study Stage 2

Summary Assessment Score

Slight beneficial

Qualitative Comments

The above assessment is applicable to both drivers and cyclists/ pedestrians unless otherwise stated. See Outline Business Case report.

TAG Severance Impacts Worksheet

Change in Severance	Population Affected			Total Affected
	PENDOYLAN	CLAWDD COCH		
Large negative				
Moderate negative				
Slight negative				
Neutral				
Slight positive	127	35		162
Moderate positive				
Large positive				

Reference Source

Google Maps
 10013270-ARC-XX-XX-RP-HE-0001 - M4 J34 - A48 WeITAG Study Stage 2
 DMRB 11.3.8

Summary Assessment Score

Slight positive

Qualitative Comments

See Outline Business Case report.