

Access Improvement Grant.

St Andrew FP S1/1/1	construction of footpath	Dinas Powys
Network Improvements County Wide	Replacing failed stiles with kissing gates	Ystrad Owen Cowbridge
Footpath L4/60/1	Repair collapsed stone stile	Llanblethian
Footpath B1/62/1	construction of steps and Handrail	Barry

Wales Coat Path Maintenance

Wales Coast Path	20 km x 2 Vegetation Clearance	Vale Coastal Corridor
Lavernock 7	Realignment of Footpath	Lavernock
St Donats 6	Roll Back	St Donats
Urban Sections	Way marking	Barry and Penarth
Wales Coast Path	Drainage and resurfacing of Wales coast Path	Lavernock

PROW Maintenance


Work detailed below has been completed by a combination of work contracted out and work completed by Vale of Glamorgan Countryside Rangers

Installation of Kissing Gates to replace existing stiles	40	PROW Network across Local Authority Area
Installation of two in one gates to replace failed stiles	15	PROW Network across Local Authority Area
Installation of Footbridges to replace dangerous structures	4	Aberthin Wenvoe Penmark
Vegetation clearance of inland path network	35 km	PROW Network across Local Authority Area

Volunteers

Walk and Clear	Promoted Routes	Valeways
Path Inspection Reports	75	Valeways
Walk and Clear	Promoted Routes	VOG Ramblers

Access Improvement Grant



St. Andrews footpath improvements (before & after)

Network Improvements



Poor condition of existing stiles - badly deteriorated



New kissing gates installed – galvanized steel




Replacement of old stone style

Handrail and step construction



Step and handrail replacements

Footbridge Installation



Wales Coast Path

